

TABLE OF CONTENTS

EXECUTIVE SUMMARY

	Page No.
CHAPTER 1 Project Description	
1.1 Project Background	Ch1-1
1.1.1 Background of the Project	1-1
1.1.2 Profile of the Proponent	1-1
1.2 Project Location and Area	1-1
1.2.1 Location	1-1
1.2.2 Accessibility	1-4
1.2.3 Proof of Authority over the Proposed Project Site	1-4
1.2.4 Predicted Impact Area	1-4
1.3 Project Rationale	1-10
1.4 Project Alternatives	1-10
1.5 Project Components	1-13
1.5.1 Use of Port Facility	1-19
1.5.2 Support Facilities	1-19
1.5.3 Power Requirement	1-19
1.5.4 Water Requirement	1-20
1.5.5 Fuel Requirement	1-20
1.5.6 Waste and Wastewater Generation	1-20
1.5.7 Transport System	1-20
1.6 Process/technology	1-22
1.6.1 Process of Operation	1-22
1.6.2 Pollution Control Devices	1-24
1.6.3 Waste Management System	1-24
1.7 Project Size	1-24
1.8 Development Plan, Description of Project Phases and Corresponding Timeframe	1-25
1.8.1 Pre-Construction Phase	1-25
1.8.2 Construction Phase	1-28
1.8.3 Operation Phase	1-30
1.8.4 Abandonment Phase	1-32
1.9 Manpower Requirement	1-32
1.10 Project Investment Cost	1-32
CHAPTER 2 Assessment of Environmental Impacts	
2.1 Land	
2.1.1 Land Use and Classification	Ch2-1
2.1.2 Geology	2-8
2.1.3 Pedology	2-48
2.1.4 Terrestrial Ecology	2-51
2.2 Water	
2.2.1 Hydrology	2-57
2.2.2 Oceanography	2-60
2.2.3 Water Quality	2-84
2.2.4 Freshwater Ecology	2-88

2.2.5	Marine Ecology	
2.3	Air	
2.3.1	Meteorology/Climatology	2-97
2.3.2	Air Quality and Noise	2-106
2.4	People	
2.4.1	Socio-economics	2-115

CHAPTER 3 Environmental Management Plan

CHAPTER 4 Environmental Risk Assessment (ERA) & Emergency Response Policy and Guidelines

4.1	Environmental Monitoring Plan	Ch4-1
4.1.1	Objectives	4-2
4.1.2	Scope and Limitations	4-2
4.2	ERA Conceptual Framework	4-2
4.2.1	The Environmental Risk Assessment Process	4-2
4.2.2	The ERA Framework	4-2
4.3	ERA Scoping and Risk Screening of Hazardous Substances	4-3
4.4	ERA Methodology	4-4
4.4.1	Consequence Severity Analysis	4-4
4.4.2	Probability/Frequency Analysis	4-5
4.4.3	Risk Categorization	4-5
4.5	Hazard Identification and Risk Characterization	4-6
4.5.1	Hazards List, Consequence and Frequency Ratings and Indicative Risks	4-6
4.5.2	Risk Characterization	4-7
4.6	Risk Management	4-7
4.6.1	Safety Policies and Guidelines	4-16
4.6.2	Emergency Preparedness and Response Team	4-16
4.7	Summary and Conclusion	4-17

CHAPTER 5 Social Development Plan/Framework (SDP) and IEC Framework

5.1	Social Development Plan	Ch5-1
5.1.1	Proposed Social Development Plan	5-1
5.2	Information, Education, and Communication (IEC) Framework	5-6

CHAPTER 6 Environmental Compliance Monitoring

6.1	Environmental Monitoring Plan	Ch6-1
6.2	Self-Monitoring Plan	6-5
6.3	Multi-Sectoral Monitoring Framework	6-5
6.4	Environmental Monitoring Framework	6-5
6.5	Environmental Guarantee Fund	6-6

CHAPTER 7 Decommissioning/Abandonment/Rehabilitation Policy

7.1	General Description	Ch7-1
7.2	Decommissioning of the Terminal	Ch7-1

CHAPTER 8 Institutional Plan for EMP Implementation

8.1	Corporate Environmental Policy	Ch8-1
8.2	Environmental Management Unit	8-2
8.3	Community Relations Office	8-2
8.4	Health and Safety Office	8-3

LIST OF TABLES

No.	Title	Page No.
1.2.1	Project components and area tabulation	Ch1-4
1.2.2	Geographic coordinates of Philcement’s leased development area	1-4
1.4.1	Project alternatives of the Proposed Philcement Davao Cement Terminal and Packaging Facility Project	1-10
1.5.1	Philcement Davao Cement Terminal and Packaging Facility Project component and area tabulation	1-14
1.5.2	List of equipment that will be utilized by Philcement Davao Cement Terminal and Packaging Facility Project	1-16
1.6.1	Pollution control equipment/devices	1-24
1.7.1	Project size description of the proposed Philcement Davao Cement Terminal and Packaging Facility Project	1-24
1.9.1	Manpower requirements for the development of Philcement Davao Cement Terminal and Packaging Facility Project	1-32
1.9.2	Manpower requirements for the operation of Philcement Davao Cement Terminal and Packaging Facility Project	1-32
2.1.1	Land Use of Davao City in 2011	2-2
2.1.2	Land Use Area, Distribution and Percent to Total (2013-2022)	2-2
2.1.3	Land Use of Davao City in 2011	2-3
2.1.4	Impacts assessment on land use and classification	2-4
2.1.5	Stratigraphic column of Central Mindanao Arc	2-15
2.1.6	Earthquake intensity	2-19
2.1.7	Estimated PGA Values for the proposed project site relative to some active seismic source zones using the Fukushima and Tanaka (1990) Attenuation relation	2-21
2.1.8	Philippine earthquake intensity scale	2-22
2.1.9	Impacts assessment on geology	2-38
2.1.10	Soil Types in Davao City lifted from the Ecological Profile of Davao City	2-48
2.1.11	Land capability classification of Davao City	2-50
2.1.12	Impacts assessment on pedology	2-50
2.1.13	List of flora species recorded during the terrestrial flora assessment	2-50
2.1.14	List of wildlife species observed within and adjacent to the project area	2-53
2.1.15	Impacts assessment on terrestrial ecology	2-56
2.2.1	Impacts assessment on hydrology	2-59
2.2.2	Summary of Tidal Constituents for Davao Gulf, and typical tidal types defined by Form Number (inset)	2-63
2.2.3	Impacts assessment on physical oceanography	2-71
2.2.4	Geographical coordinates of the water quality sampling stations	2-84
2.2.5	Result of the marine water quality analysis, March 17, 2021	2-86
2.2.6	Impacts assessment on water quality	2-87
2.2.7	Sampling sites for the monitoring activity, April 2021	2-88
2.2.8	Benthic component composition of the sampling sites for the proposed Philcement Davao Cement Terminal and Packaging Facility Project, April 2021	2-92
2.2.9	Phytoplankton profile of the sampling sites, April 2021	2-93

2.2.10	Zooplankton profile of the sampling sites, April 2021	2-94
2.2.11	Fishery profile of the sampling sites for the Philcement monitoring program, April 2021	2-94
2.2.12	Impacts assessment on marine ecology	2-96
2.3.1	Impact assessment and mitigation for climate/meteorology	2-103
2.3.2	CLIRAM* of the projected seasonal change in total rainfall (in millimeters) in 2036-2065 for Davao del Sur; baseline period: 1971-2000	2-105
2.3.3	CLIRAM* of the projected seasonal change in mean temperature (in degree Celsius) in 2036-2065 for Davao del Sur; baseline period: 1971-2000	2-105
2.3.4	National Ambient Air Quality Guideline Values (NAAQGV) for criteria pollutants	2-106
2.3.5	Ambient air sampling stations	2-106
2.3.6	Source characteristics during construction and operation	2-108
2.3.7	Source characteristic of the proposed conveyor belts	2-109
2.3.8	Noise sampling stations	2-109
2.3.9	Philippine noise criteria at different land uses, dBa	2-109
2.3.10	Industries around the proposed project site	2-110
2.3.11	One- (1-) hour concentration of pollutants at the sampling stations	2-111
2.3.12	24-hour concentration of TSP at the sampling stations	2-111
2.3.13	Measured sound levels at the sampling stations	2-112
2.3.14	Impact assessment and mitigation for air quality	2-112
2.4.1	Schedule of the conducted KIIs, FGDs and household surveys	2-116
2.4.2	Population of Davao City	2-118
2.4.3	Age group, Davao City	2-119
2.4.4	Working age population by gender	2-119
2.4.5	Working age population	2-119
2.4.6	Religious affiliation	2-119
2.4.7	Household population by ethnicity	2-120
2.4.8	Marital status	2-121
2.4.9	Average family income and expenditures, 2012 and 2015	2-121
2.4.10	Foreign Trade in US million dollars	2-121
2.4.11	Financial institutions	2-122
2.4.12	Tourism industry	2-122
2.4.13	Internal Revenue Allotment (IRA) shares of the Government of Davao City	2-122
2.4.14	Leading causes of morbidity, 2019	2-123
2.4.15	Fifteen leading causes of mortality, 2019	2-123
2.4.16	Water source	2-124
2.4.17	Davao City Water Supply, Davao City Water District, 2014-2018	2-124
2.4.18	Access to Water to safe water supply in Davao City, 2019	2-125
2.4.19	Households with sanitary toilets	2-125
2.4.20	Households with satisfactory solid waste disposal	2-125
2.4.21	Total population and tribal affiliation	2-127
2.4.22	School levels, and number of children and youth in and out of school	2-127
2.4.23	Functionality of recreational and other developmental facilities	2-128
2.4.24	Barangay Ilang revenue	2-128
2.4.25	Sources of water	2-128

2.4.26	Causes of Morbidity in 2019	2-129
2.4.27	Mortality in 2019	2-129
2.4.28	Gender of respondents	2-129
2.4.29	Age of respondents (years old)	2-130
2.4.30	Civil status of respondents	2-130
2.4.31	Religious affiliation	2-130
2.4.32	Educational attainment of respondents	2-130
2.4.33	Availability of income sources of respondents	2-131
2.4.34	Sources of income	2-131
2.4.35	Place of work of respondents	2-132
2.4.36	Monthly income of respondents	2-132
2.4.37	Respondent's involvement in other sources of income	2-132
2.4.38	Other sources of income	2-132
2.4.39	Respondent's monthly income from other sources	2-133
2.4.40	Number of respondent's household members	2-133
2.4.41	Information on respondent's household members	2-133
2.4.42	Age of household members of respondents	2-134
2.4.43	Income source of household member	2-134
2.4.44	Income contribution of respondent's household member per month (PhP)	2-135
2.4.45	Ethnic group	2-135
2.4.46	Respondent's Ethnic group	2-135
2.4.47	Spoken language in the respondent's household	2-136
2.4.48	Availability of other sources of income to household members	2-136
2.4.49	Other sources of income of household members	2-136
2.4.50	Monthly household expenses	2-137
2.4.51	Where household essentials are purchased	2-137
2.4.52	Source of drinking water	2-137
2.4.53	Household connection to power source	2-138
2.4.54	Source of power	2-138
2.4.55	Monthly electricity expenses	2-138
2.4.56	Source of lighting if not connected to a main power source	2-138
2.4.57	Monthly expense for other sources of lighting	2-139
2.4.58	Fuel for cooking	2-139
2.4.59	Household appliances/consumer durables	2-139
2.4.60	Have toilet facilities	2-140
2.4.61	Type of toilet facilities	2-140
2.4.62	House ownership	2-140
2.4.63	Arrangements in dwelling place	2-140
2.4.64	Lot ownership	2-140
2.4.65	Land owner	2-141
2.4.66	Payment for land occupancy	2-141
2.4.67	Monthly payment for land occupancy	2-141
2.4.68	Roof materials	2-141
2.4.69	Wall materials	2-142
2.4.70	Years residing in the barangay	2-142
2.4.71	Place of origin	2-142

2.4.72	Reason for migrating	2-143
2.4.73	Membership in organization	2-143
2.4.74	Place where respondents seek medical attention	2-144
2.4.75	Place where respondents seek medical attention	2-144
2.4.76	Positive attributes of the barangay	2-144
2.4.77	Livelihood/ income sources of women in the barangay	2-145
2.4.78	Occurrence of women-related problems	2-145
2.4.79	Occurrence	2-145
2.4.80	Activities women can pursue in community development	2-145
2.4.81	Common youth activities in the barangay	2-146
2.4.82	Possibility of performing other activities by the youth as their contribution to community development	2-146
2.4.83	Other youth activities towards community development	2-146
2.4.84	Most common illnesses of respondents, household members in the last five (5) years	2-147
2.4.85	Where medical attention was sought	2-148
2.4.86	Where medicine is sourced	2-148
2.4.87	Source of funds for medical expenses	2-149
2.4.88	Yearly medical expenses	2-149
2.4.89	Medical services or medical missions encountered	2-149
2.4.90	Common causes of death in the barangay over the last five (5) years	2-150
2.4.91	Smoking	2-150
2.4.92	Since when respondent has been smoking	2-150
2.4.93	Alcohol	2-150
2.4.94	Frequency of drinking alcohol	2-151
2.4.95	Birth control	2-151
2.4.96	Birth control method	2-151
2.4.97	Water source for bathing and laundry	2-151
2.4.98	Water source for drinking and cooking	2-152
2.4.99	Method of garbage disposal	2-152
2.4.100	Waste segregation	2-152
2.4.101	Whether changes were observed in the barangay over the last five (5) years	2-153
2.4.102	Observed changes	2-153
2.4.103	Reasons for changes	2-153
2.4.104	Time/period when changes were observed	2-154
2.4.105	Most common problems encountered in the barangay based on environmental aspects	2-154
2.4.106	Entities that provided assistance to address problems	2-154
2.4.107	Problems given attention	2-155
2.4.108	Assistance extended	2-155
2.4.109	Contentment with the state of the environment	2-155
2.4.110	Suggested mitigating measures to address the present state of the environment	2-156
2.4.111	Natural calamities that occurred in the barangay in the past five (5) years	2-156

2.4.112	Awareness of Philcement Corporation	2-157
2.4.113	Sources of information about the company	2-157
2.4.114	Awareness of the proposed Philcement Davao Terminal and Packaging Facility Project	2-157
2.4.115	Sources of information	2-158
2.4.116	Knowledge about the activities of the proposed Davao Cement Terminal and Packaging Facility Project	2-158
2.4.117	Whether the proposed project will bring about positive impacts	2-158
2.4.118	Perceived positive impacts	2-158
2.4.119	Benefits presently derived from other private companies in the area	2-159
2.4.120	Benefits from other private companies	2-159
2.4.121	Suggestions to enhance the perceived positive impacts	2-160
2.4.122	Whether proposed project will bring negative impacts to the community	2-160
2.4.123	Perceived negative impacts	2-160
2.4.124	Suggestions to address the perceived negative impacts	2-161
2.4.125	Overall perception about the proposed project	2-161
2.4.126	Attitude toward the proposed project	2-161
2.4.127	Whether willing to be involved in determining monitoring results of the project	2-162
2.4.128	Willingness to attend meetings called by Philcement Corporation and the barangay regarding company regulations and social development projects and other IEC activities	2-162
2.4.129	Whether in agreement to the establishment of a grievance mechanism	2-162
2.4.130	How the grievance mechanism may be implemented	2-163
2.4.131	Reasons for not agreeing to have a grievance mechanism	2-163
2.4.132	Whether the proposed project will provide additional employment in the community	2-163
2.4.133	Impacts assessment on socio-economics	2-163
3.1	Proposed environmental management plan for the Philcement Davao Cement Terminal and Packaging Facility Project	3-1
3.2	Target efficiency of project mitigating measures	3-7
4.1	The Consequence Severity Rating Chart used in Consequence Analysis	4-5
4.2	The Probability of Occurrence Rating Chart used in Consequence Analysis	4-5
4.3	Risk Matrix	4-6
4.4	Philcement Davao Cement Terminal Project Hazards List and Risk Characterization	4-8
4.5	Identified hazards and proposed mitigating measures	4-18
5.1	Social Development Plan Framework	5-4
5.2	Proposed IEC framework for the Davao Cement Terminal and Packaging Facility Project	5-7
6.1	Proposed Environmental Monitoring Plan (EMoP)	6-3
6.2	Proposed MMT members	6-5
6.3	Proposed self-monitoring activities for the Philcement Davao Cement Terminal and Packaging Facility Project	6-5

LIST OF FIGURES

No.	Title	Page No.
1.2.1	Location map of the proposed Philcement Davao Cement Terminal and Packaging Facility Project	Ch1-2
1.2.2	Vicinity map of the proposed Philcement Davao Cement and Packaging Facility Terminal Project	1-3
1.2.3	Projection of the area of the proposed Philcement Davao Cement Terminal and Packaging Facility Project using Google Earth	1-6
1.2.4	Satellite image of the host community of the proposed area of the project	1-7
1.2.5	Impact area of the Proposed Davao Cement Terminal and Packaging Facility	1-8
1.2.6	Impact area of the Proposed Davao Cement Terminal and Packaging Facility in terms of Socio-economic benefits	1-9
1.5.1	Site development plan of the proposed Philcement Davao Cement Terminal and Packaging Facility Project	1-15
1.5.2	Traffic flow of trucks	1-21
1.6.1	Process flow diagram	1-23
1.6.1	Mass balance	1-22
1.8.1	Construction site development plan	1-27
1.8.2	Gantt chart of the proposed Philcement Davao Terminal and Packaging Facility Project development	1-31
2.1.1	Zoning map of Bunawan District, Davao City (<i>Source: City Planning and Development Office of the City Government of Davao</i>)	2-6
2.1.2	Zoning classification of the Proposed Davao Cement Terminal and Packaging Facility	2-7
2.1.3	Topographic map of the proposed project site	2-10
2.1.4	Slope map of the propose project site	2-11
2.1.5	Location map of the project site on NAMRIA topographic map	2-12
2.1.6	Sketch map showing the Philippine Mobile Belt	2-13
2.1.7	Plot of seismicity in the Philippines from 1973-2006	2-14
2.1.8	Geological map of Mindanao	2-17
2.1.9	Regional geological map of the Agusan – Davao Basin	2-18
2.1.10	Map showing peak horizontal acceleration amplitudes in Soft Soil for Mindanao, Philippine region. Acceleration values have a 10% probability of exceedance in 50 years. Contours are in terms of the acceleration of gravity (g).	2-20
2.1.11	Map showing peak horizontal acceleration amplitudes in Medium Soil for Mindanao, Philippine region. Acceleration values have a 10% probability of exceedance in 50 years. Contours are in terms of the acceleration of gravity (g).	2-20
2.1.12	Map showing peak horizontal acceleration amplitudes in Rocks for Mindanao, Philippine region. Acceleration values have a 10% probability of exceedance in 50 years. Contours are in terms of the acceleration of gravity (g).	2-21
2.1.13	Epicenters of historically damaging/significant earthquakes in the Philippines	2-25

2.1.14	Mindanao portion of the distribution of active faults and trenches of the Philippines.	2-26
2.1.15	Maps showing the earthquake epicenters near the Cotabato Trench.	2-29
2.1.16	Ground shaking hazard map of Davao City.	2-30
2.1.17	Map showing the epicenters of tsunamigenic	2-31
2.1.18	Tsunami vulnerability map of the Philippines.	2-34
2.1.19	Tsunami shoaling process	2-35
2.1.20	Map showing the active and potentially active volcanoes of the Philippines	2-37
2.1.21	Liquefaction Hazard Map of Davao City.	2-45
2.1.22	Earthquake-induced landslide hazard map of Davao City	2-46
2.1.23	Ground rupture hazard map of Davao City	2-47
2.1.24	Soil map of Davao City (<i>Source: JICA, 1981</i>)	2-49
2.1.25	Terrestrial Ecology sampling map	2-52
2.2.1	Watershed map of Davao City	2-59
2.2.2	Detailed landslide and flood susceptibility map of Bunawan District (<i>portion</i>), Davao City (Merged and cropped from Sheet Nos. 4115-III-3 and 4115-III-8).	2-60
2.2.3	Generated bathymetry map of Davao Gulf	2-61
2.2.4	Tide level prediction for the month of May, 2021 in Davao IHO Tide Station	2-62
2.2.5	Predicted currents in the project area during tidal flooding (<i>amihan</i> wind condition)	2-64
2.2.6	Predicted currents in the project area during tidal flooding (<i>amihan</i> wind condition)	2-65
2.2.7	Predicted currents in the project area during transition from high tide to low tide for <i>amihan</i> wind condition	2-66
2.2.8	Predicted currents in the Bay during low tidal event (<i>amihan</i> wind condition)	2-67
2.2.9	Predicted currents in the Bay during low tidal event (<i>amihan</i> wind condition).	2-67
2.2.10	Predicted currents in the Bay during high tidal event for <i>habagat</i> wind condition (wind speed of 4 m/s blowing from the southwest).	2-68
2.2.11	Predicted currents in the Bay during high tidal event for <i>habagat</i> wind condition (wind speed of 4 m/s blowing from the southwest).	2-69
2.2.12	Predicted currents in the Bay during low tidal event for <i>habagat</i> wind condition	2-70
2.2.13	Predicted currents in the Bay during low tidal event for <i>habagat</i> wind condition	2-70
2.2.14	Hypothetical typhoon track (patterned after typhoon Pablo) used in storm surge modeling	2-79
2.2.15	Predicted water levels before the passage of storm starting at simulation time of 6:00 PM and 7:00 PM of December 03, 2012 (uppermost figures) and at 9:30 PM and 11:00 PM of the same day, (lowermost figures)	2-80
2.2.16	Snapshots of time series maps of predicted storm surges and/or water levels as the eye of the storm passes south of the project area.	2-81
2.2.17	Predicted storm surges and/or water levels during the passage of the storm offshore of the vicinity of the project area. Notice the increase	2-82

	in water levels (red areas of the project area) indicating the increase in water levels compared to surrounding areas of the larger Davao Gulf.	
2.2.18	Snapshots of maps of predicted storm surges and/or water levels after the passage of the storm.	2-83
2.2.19	Time series of predicted storm surge (red line) and the simulated tidal fluctuation under normal wind condition (blue line).	2-84
2.2.20	Sampling map for mbient water quality	2-85
2.2.21	Sampling map for the marine ecology study	2-90
2.2.22	Comparative composition of the benthos from marine monitoring sites, April 2021	2-93
2.3.1	Relative location of the proposed project site to Davao City PAGASA Synoptic Station	2-98
2.3.2	Modified Coronas Classification of Philippine Climate.	2-99
2.3.3	Normal monthly surface temperature at PAGASA Davao City Synoptic Station (1981-2010)	2-100
2.3.4	Normal monthly rainfall at PAGASA Davao City Synoptic Station (1981-2010)	2-101
2.3.5	Normal monthly relative humidity at PAGASA Davao City Synoptic Station (1981-2010)	2-102
2.3.6	Wind rose at PAGASA Davao City Synoptic Station (1981-2010)	2-103
2.3.7	Air quality sampling staation	2-107
2.3.8	Estimated one-hour TSP concentration during construction	2-114
2.3.9	Distance of maximum one-hour TSP concentration during construction is 90 m from the construction area	2-114
2.3.10	Maximum one-hour TSP concentration during operation is estimated to fall up to 451 meters from the conveyor belt	2-115
4.1	The Risk Assessment Process	4-3
4.2	ERA Scoping and Risk Screening Process	4-4
8.1	Organizational structure of Philcement Corporation	8-2

LIST OF PLATES

No.	Title	Page No.
1.5.1	Ship unloader with fully-sealed conveyor system	Ch1-17
1.5.2	Cement storage/silo	1-17
1.5.3	Cement bagging/ Rotopacker	1-18
1.5.4	Product loading: trucks and palletes	1-18
2.1.1	One of several mature Neem Tree (<i>Azadirachta indica</i>) observed at the project site	2-54
2.1.2	Other mature Neem Trees (<i>Azadirachta indica</i>) observed at the project site	2-54
2.1.3	Champagne Palm (<i>Hyoporbe indica</i>) and Coron Yucca (<i>Dracaena multiflora</i>) planted in front Union Galvasteel Plant	2-54
2.1.4	MacArthur Palm (<i>Ptychosperma macarthurii</i>) and ornamental plants such as starcluster (<i>Pentas</i> sp.) and wild cinnamon (<i>Syzigium campanulatum</i>) planted in front Union Galvasteel Plant	2-54
2.1.5	Rows of Indian Lanutan (<i>Polyalthia longifolia</i>) planted by Union Galvasteel	2-54
2.1.6	Silver Buttonwood (<i>Conocarpus erectus</i>) and Foxtail Palm (<i>Wodyetia indica</i>) planted near the accommodation area	2-54
2.1.7	On-going operation at the TEFASCO port during sampling	2-86
2.1.8	Collection of sample at MWQ3	2-86
2.1.9	Photo of ME2 relative to the coastal community (left photo)	2-91
2.1.10	Photo of ME1 relative to the loading pier of TEFASCO	2-91
2.1.11	Benthic profile from MS1. Photo on the left shows a soft coral perched on a hard substrate with organ pipe coral (red) on the foreground. Left photo shows a Fingerprint Toby (<i>Cartigaster compressa</i>) swimming over reef area.	2-96
2.1.12	Pomacentrids and Pomacanthids swarm over branching coral colonies and soft corals at MS2.	2-96

LIST OF ANNEXES

No.	Title
ES1	IEC Documentation
ES2	EMB Technical Scoping Checklist
ES3	Sworn Statement of Accountability of Philcement Corporation
ES4	Sworn Statement of Accountability of Gaia South
ES5	Pre-Scoping Survey Report
ES6	Public Scoping Report
ES7	PEMAPS Sworn Statement of Accountability of Philcement
ES8	PEMAPS
1.1	Memorandum of Agreement between Philcement and UGC
1.2	Memorandum of Agreement between Philcement and TEFASCO
1.3	Certificate of Material for Union V Super Strength 40 (Cement Type 1P) and Union V Ultra Strength 50 (Cement Type 1)
2.2.1	Results of the Water Quality Analysis
2.3.1	Davao Climatological Normals
2.3.2	Davao Climatological Extremes
2.3.3	Davao Wind Rose Diagram (1981-2010)
2.3.4	Results of the Air Quality Analysis
2.4.1	Household Perception Survey Questionnaire